



GMP 1400ES

INSTALLATION PLAN


FRONT






SIDE



TOP



WHAT YOU NEED

Electrical cable + industrial plug			
	V.230/1/50-60Hz	V.230/3/50-60Hz	V.400/3N/50-60Hz
	34 Amps	20 Amps	13 Amps
Total power required	7,83 kW	7,83 kW	7,83 kW
Differential magnetothermal switch	I _{dn} = 0.03 Amps	I _{dn} = 0.03 Amps	I _{dn} = 0.03 Amps
Ducting	optional Ø70 mm, 30 m ³ /h	optional Ø70 mm, 30 m ³ /h	optional Ø70 mm, 30 m ³ /h
Clearance around the ironer	back: 400 mm - right: 650 mm - left: not needed		